

Makdata

Datum	Zeit	Querschnitt	Querschnitt	Querschnitt	Querschnitt	Querschnitt	Querschnitt	Spur1 Ges
22.10.18	00:00	45	13	32	0	0	0	45
23.10.18	00:00	145	33	111	1	0	0	145
24.10.18	00:00	179	67	111	1	0	0	179
25.10.18	00:00	160	46	113	1	0	0	160
26.10.18	00:00	187	51	135	1	0	0	187
27.10.18	00:00	142	87	50	4	1	0	142
28.10.18	00:00	78	46	32	0	0	0	78
29.10.18	00:00	51	28	23	0	0	0	51

Makdata

Spur1 Ges	Spur1 Ges	Spur1 Ges	Spur1 Ges	Spur1 Ges	Spur1 KLE	Spur1 KLE	Spur1 KLE	Spur1 KLE
28	38	43	55	35	13	28	33	38
23	33	38	50	31	33	23	33	38
23	33	38	50	30	67	23	28	33
28	33	38	55	32	46	23	33	38
28	33	38	60	33	51	23	33	38
23	33	38	50	32	87	23	33	38
28	33	38	55	33	46	23	33	38
23	33	38	50	31	28	23	28	38

Makdata

Spur1 KLE	Spur1 KLE	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 VAN
40	33	32	28	38	43	55	37	0
45	30	111	23	33	38	50	32	1
50	28	111	28	33	38	50	32	1
45	30	113	28	33	38	55	33	1
55	31	135	28	33	38	60	34	1
45	32	50	28	33	43	50	34	4
50	31	32	28	33	43	55	36	0
45	30	23	28	33	38	50	33	0

Makdata

Spur1 VAN	Spur1 VAN	Spur1 VAN	Spur1 VAN	Spur1 VAN	Spur1 LKW	Spur1 LKW	Spur1 LKW	Spur1 LKW
0	0	0	0	0	0	0	0	0
18	18	18	20	18	0	0	0	0
28	28	28	30	28	0	0	0	0
48	48	48	50	48	0	0	0	0
23	23	23	25	23	0	0	0	0
23	28	28	30	26	1	23	23	23
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur1 LKW	Spur1 LKW	Spur1 LZ A	Spur1 LZ v	Spur1 LZ v	Spur1 LZ v	Spur1 LZ v	Spur1 LZ v	Spur2 Ges
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
25	23	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur2 Ges	Spur2 Ges	Spur2 Ges	Spur2 Ges	Spur2 Ges	Spur2 KLE	Spur2 KLE	Spur2 KLE	Spur2 KLE
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur2 KLE	Spur2 KLE	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 VAN
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur2 VAN	Spur2 VAN	Spur2 VAN	Spur2 VAN	Spur2 VAN	Spur2 LKW	Spur2 LKW	Spur2 LKW	Spur2 LKW
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0



Makdata

Spur2 LKW	Spur2 LKW	Spur2 LZ A	Spur2 LZ v	Spur2 LZ v	Spur2 LZ v	Spur2 LZ v	Spur2 LZ v Ø
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0