

Makdata

Datum	Zeit	Querschnitt	Querschnitt	Querschnitt	Querschnitt	Querschnitt	Querschnitt	Spur1	Ges
22.10.18	00:00	45	13	32	0	0	0		45
23.10.18	00:00	11	2	9	0	0	0		11

Makdata

Spur1 Ges	Spur1 Ges	Spur1 Ges	Spur1 Ges	Spur1 Ges	Spur1 KLE	Spur1 KLE	Spur1 KLE	Spur1 KLE
28	38	43	55	35	13	28	33	38
33	33	38	45	34	2	33	33	38

Makdata

Spur1 KLE	Spur1 KLE	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 PKW	Spur1 VAN
40	33	32	28	38	43	55	37	0
40	35	9	18	33	43	45	34	0

Makdata

Spur1 VAN	Spur1 VAN	Spur1 VAN	Spur1 VAN	Spur1 VAN	Spur1 LKW	Spur1 LKW	Spur1 LKW	Spur1 LKW
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur1 LKW	Spur1 LKW	Spur1 LZ A	Spur1 LZ v	Spur1 LZ v	Spur1 LZ v	Spur1 LZ v	Spur1 LZ v	Spur2 Ges
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur2 Ges	Spur2 Ges	Spur2 Ges	Spur2 Ges	Spur2 Ges	Spur2 KLE	Spur2 KLE	Spur2 KLE	Spur2 KLE
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur2 KLE	Spur2 KLE	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 PKW	Spur2 VAN
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur2 VAN	Spur2 VAN	Spur2 VAN	Spur2 VAN	Spur2 VAN	Spur2 LKW	Spur2 LKW	Spur2 LKW	Spur2 LKW
0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0

Makdata

Spur2 LKW	Spur2 LKW	Spur2 LZ A	Spur2 LZ v	Spur2 LZ v	Spur2 LZ v	Spur2 LZ v	Spur2 LZ v Ø
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0